REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and lifting equipment regulation 1998 (Regulations 9) Employer (and or plant owner.) Philip Shovlin Plant Hire LTD Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU Address at which the examination was made. As above Description of lifting equipment. 360 Tracked Hydraulic Excavator Distinguishing Number DCH13U0266 Makers Name. CASE Year of Manufacture. N/K SWL & Configuration. See load Chart Fleet No CX266 Nature of Examination. 9(1) 9(2)9(3)(a)(i)9(3)(a)(ii) 9(3)(a)(iii) 9(3)(a)(iv)Particulars of any test. None Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass Y/N **Auxiliary Lifting Point** Good 4000kgs YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Geith Q/Hitch S/N 5522255 Good 5000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or

within a specified time.

Other defects and remedies

None

Date of last thorough examination.

04.01.18

Latest date by which the next thorough examination must be carried out.

22.12.19

Date of thorough examination.

23.12.18

I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted in this report, which are or could become a danger to persons, the equipment is safe to operate.

Name and Addre Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester.

Signatule

Date 23.12.18

Qualifications. Fitter

Name and Address of person authenticating report if different from above

Signature

Date 23.12.18

Date of report 23.12.18

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01