Record No DS 2357

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and lifting equipment regulation 1998 (*Regulations 9*)

Employer (and or plant owner.) Philip Shovlin Plant Hire LTD

Address. The Brook Business Complex
Bennett Street
West Gorton
Manchester M12 5AU

Address at which the examination was made. As above

Description of lifting equipment. 360 Wheeled Hydraulic Excavator. Distinguishing Number K119110
Makers Name. LIEBHERR Year of Manufacture. N/K
SWL & Configuration. See load Chart Fleet No Giga L - 9110

Nature of Examination .	9(1)	9(2)	9(3)(a)(i)	9(3)(a)(ii)	9(3)(a)(iii)	9(3)(a)(iv)
				X		

Particulars of any test. None

Observations and conditions of ropes, chains, attachments etc.

Description	Condition	WLL	Pass Y/N
Auxiliary Lifting Point	Good	7500KGS	YES
RCI (for Test Load Results see SP-LAFT 01)	Good	N/A	YES
DIPPER PIN	Good	10000Kgs	YES

Identification of any part found to have a defect which is or could become a danger to persons.

None

State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time.

None.

Other defects and remedies

None

Date of last thorough examination. 25.05.21

Latest date by which the next thorough examination must be carried out. 18.05.23

Date of thorough examination. 19.05.22

I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.
Name and Address of Competent Person. Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester.
Signature

Date 19.05.22

Qualifications. Fitter

Name and Address of person authenticating report if different from above

Signature Date 19.05.22

Date of report 19.05.22