Record No DS 2383

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU Address at which the examination was made. As above Description of lifting equipment. 360 Wheeled Hydraulic Excavator TEREX SWL & Configuration. TEREX SWL & Configuration. 9(1) 9(2) 9(3)(a)(i) 9(3)(a)(ii) 9(3)(a)(ii) 9(3)(a)(iii) Particulars of any test. None Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass Y/N Good 5000kgs YES RCI (for less Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date of thorough examination. 22.02.23 Date of port 09.01.23 Date of port 09.01.23	Employer (and or plant of	owner.) Philip Sho	ovlin Plant H	lire L	ΓD					
Description of lifting equipment. TREEX TREEX See load Chart TREEX See load Chart	Bennett Stree West Gorton Manchester	et								
Makers Name. SwL & Configuration. See load Chart See load Chart Particulars of Manufacture. Pleet No Particulars of Agnufacture. Pleet No Particulars of any test. None Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass YN Good Soulds Hitch Serial No 270770 Good Soulds Hitch Serial No 270770 Good Auxiliary Lift point Hook & Shackle Assembly Good M/A WES Auxiliary Lift point Hook & Shackle Assembly Good Mone State description of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 21.02.22 Latest date by which the next thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this proof which are of ould become a danger to persons, the equipment is safe to operate. Name and Address of Dometent Jesson Danian Schoffeld. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Date 09.01.23		As above								
Particulars of any test. None Secription Secription Secription of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None State description of last thorough examination. Secription Secription Secription of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. Ogo.1.23	Makers Name. TEREX							Year of Manufacture. N/K		
Observations and conditions of ropes, chains, attachments etc. Description Condition WLL Pass Y/N Quick Hitch Serial No 270770 Good 5000kgs YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 09.01.23 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this proper which are of ould become a danger to persons, the equipment is safe to operate. Name and Address of form fetent ferson Danian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23	Nature of Examination.	9(1)	9(2)		9(3)(a)(i)	9(3		9(3)(a)(iii)	9(3)(a)(iv)	
Description Condition WLL Pass Y/N Quick Hitch Serial No 270770 Good 5000kgs YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 09.01.23 I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this feport which are of could become a danger to persons, the equipment is safe to operate. Name and Address of person authenticating report if different from above Signature Date 09.01.23 Date 09.01.23	Particulars of any test. None									
Quick Hitch Serial No 270770 Good 5000kgs YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this proper which are of could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Jerson Daminan Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23	Observations and conditi	ons of ropes, chains	, attachment	s etc.						
Quick Hitch Serial No 270770 Good 5000kgs YES RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this proper which are of could become a danger to persons, the equipment is safe to operate. Name and Address of Competent Jerson Daminan Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23					dition			TYPY Y	DSIAI	
RCI (for Test Load Results see SP-LAFT 01) Good N/A YES Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this lepopt which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent lerson) Danian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23		70770			*					
Auxiliary Lift point Hook & Shackle Assembly Good 10000Kgs YES Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate. Name and Address of person authenticating report if different from above Signature Date 09.01.23 Date 09.01.23									— 	
Identification of any part found to have a defect which is or could become a danger to persons. None State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time. None. Other defects and remedies None Date of last thorough examination. 21.02.22 Latest date by which the next thorough examination must be carried out. 08.01.24 Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this popyr which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent ferson Danian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Oualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23				· · · · · · · · · · · · · · · · · · ·				 	***	
Date of last thorough examination. Latest date by which the next thorough examination must be carried out. Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this peper, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of Completent Jerson Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23	State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time.									
Date of last thorough examination. Latest date by which the next thorough examination must be carried out. Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this peport, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent person Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23	Other defects and remedi	es								
Latest date by which the next thorough examination must be carried out. Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent ferson Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23		None								
Date of thorough examination. 1 certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent terson Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Name and Address of person authenticating report if different from above Signature Date 09.01.23	Date of last thorough examination.								21.02.22	
I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent ferson Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Name and Address of person authenticating report if different from above Signature Date 09.01.23	Latest date by which the next thorough examination must be carried out.						08.01.24			
to defects noted on this report, which are of could become a danger to persons, the equipment is safe to operate. Name and Address of competent ferson Damian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester. Signature Date 09.01.23 Name and Address of person authenticating report if different from above Signature Date 09.01.23	Date of thorough examination.								09.01.23	
Qualifications. Fitter Name and Address of person authenticating report if different from above Signature Date 09.01.23	to defects noted on this name and Address of co	eport, which are of	ould become	e a da	nger to persons,	the equ Comple	ipment is s ex, Bennett	afe to operate.		
Signature Date 09.01.23	Qualifications. Fitter	-								
	Name and Address of person authenticating report if different from above									
Date of report 09.01.23	Signature			Date 09.01.23						
	Date of report 09.01.23		-							

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01