Record No DS 2389

## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer	(and or plant o	wner.) Philip S	Shovlin Plant	Hire L	TD			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Address.	The Brook B Bennett Stree West Gorton Manchester								
	t which the on was made.								
Description of lifting equipment.  Makers Name.  SWL & Configuration.  360 Wheeled Hydral LIEBHERR See load Chart					aulic Excavator			Distinguishing Num Year of Manufacture Fleet No	
Nature of	Examination .	9(1)	9(2)		9(3)(a)(i)	9(3)	)(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particular	s of any test.	None			<u> </u>	1			
Observati	ons and condition	ons of ropes, chai	ns, attachme	nts etc.			***************************************		
Description				Con	dition			WLL	Pass Y/N
Auxiliary Lifting Point			Good				7500KGS	YES	
RCI (for Test Load Results see SP-LAFT 01)				Good				N/A	YES
DIPPER PIN				Good				10000Kgs	YES
Geth Quick Hitch				Goo	Good			10500Kgs	YES
within a s <sub>l</sub>	pecified time.	None.	air or renewa	or alte	rations required	to reme	edy the de	fect either immedia	itely or
		None							
Date of last thorough examination.								12.04.22	
Latest date by which the next thorough examination must					irried out.				02.04.24
Date of thorough examination.						****			03.04.23
to defects	noted on this re	port, which are o	r could becor	me a da	nger to persons,	the equ Comple	ipment is ex, Benne	tt Street, West Gort	
Qualifications. Fitter						Date	03.04.2	3	
Name and	Address of per	son authenticatin	g report if dit	fferent f	from above				
Signature						Date	03.04.23	3	
Date of re	port 03.04.23								
							Issue N	lo:	1

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01