Record No DS 2407

## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant o	wner) Philin Sho	ovlin Plant H	lire L	TD				
	usiness Complex et							
Address at which the examination was made.	As above							
Description of lifting equipment. 360 Tracked Hydrar Makers Name. Takeuchi SWL & Configuration. Refer to duty chart				Yea			stinguishing Number 125005668 ar of Manufacture. 2017 et No TB250-668	
Nature of Examination .	9(1)	9(2)		9(3)(a)(i)	9(3	)(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test.	None				L.			
Observations and condition	ons of ropes, chains	s, attachmen	ts etc.	***************************************				
Description			Condition				WLL	Pass Y/N
Auxiliary Lifting Point			Good				4000kgs	YES
Height and Slew Limiter			N/A			N/A	N/A	
Hill Quick Hitch TB250-	3CX TEFRA S/N 7	78716	Good			4000kgs	YES	
State description of the dwithin a specified time.	None efect and any repair None.	or renewal	or alte	erations required	to reme	edy the defe	ect either immedi	ately or
Other defects and remedi	es							<del></del>
	None							
Date of last thorough examination.								06.10.22
Latest date by which the next thorough examination mus				arried out.				01.10.24
Date of thorough examination.								02.10.23
I certify that the above ecto defects noted on this re Name and Address of Co Signature	eport, which are or	could becom	ie a da	anger to persons,	the equ Comple	ipment is s	afe to operate.	
Qualifications. Fitter								
Name and Address of per	rson authenticating	report if diff	ferent	from above				
Signature					Date	02.10.23		
Date of report 02.10.23								· · · · · · · · · · · · · · · · · · ·

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01