



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/6792-6.

Volvo Crane Wagon PO68.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains -8mm 2-Leg Chain- 7mm 2-Leg Chain- 3t Web Sling – Bucket Chain – 10mm 2-Leg Chain Slings -10mm Tamper Chain – Fall Arrest Block – Safety Harnes – Lanyard.

Identification mark of the equipment. 10mm Lashing Chains SRH/0037-SRH/0038-2967-2968-2966-0026F 2966F – 8mm 2-Leg Chain 160320 – 7mm 2-Leg Chain SP1016 – 10mm 2-Leg Chain Slings PO70 – PO68 SRH/0035-10mm Bucket Chain SRH/62-10mm Tamper Chains TO1 – TO2 – Fall Arrest Block 8676100 Safety Harness 23559295- Lanyard 23558409 – Mini Digger Web Sling AF3S 0918.

Shared Trailer Chains. 10mm 1-Leg Chain Sling – SP 1126 – SP 1127 – SP 1128 – SP 1129.

Date of last thorough examination. Not Known.

No. of report issued on that date. Not Known.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn. 7mm 2-Leg Chain 2.12t – Bucket Chain 3.15t – 8mm 2-Leg Chain Sling 2.8t – 10mm 2-Leg Chain Slings 3.15t Tamper Chains 63 Kn – Fall Arrest Block 140kg- Safety Harness – Lanyard 140kg – Mini Digger Web Sling 3t Shared Trailer 10mm 1-Leg Chain Slings 3.15t.

Details of any defects found (if any state). None.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 12-JUNE-2024, that the above particulars are correct.

Date for completion of next thorough examination. 12-DECEMBER2-2024.

Signature of Competent Person.

Date. 12-JUNE-2024.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/6792-8.

Scania Crane Wagon P1 SHV.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains -10mm 2-Leg Chains-10mm -10mm Bucket Chain-

Identification mark of the equipment. 10mm Lashing Chains 0026I-0026J-0026G-0026E-2965 – 10mm Bucket Chain SRH/61- 10mm 2-Leg Chain Slings SRH/0050 – 0723 – 0724.

Shared Trailer Chains 10mm 1-Leg Chain Slings. SP1126 – SP 1127 – SP 1128 – SP1129.

Date of last thorough examination. Not Known.

No. of report issued on that date. Not Known.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn.
10mm 2-Leg Chain Sling 3.15t
10mm Bucket Chain 3.15t.

Details of any defects found (if any state). None. 10mm 1-Leg Chain Slings. 3.15t.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 12-JUNE-2024, that the above particulars are correct.

Date for completion of next thorough examination. 12-DECEMBER2-2024.

Signature of Competent Person.

Date. 12-JUNE-2024.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/6792-7.

Volvo Crane Wagon PN71 Steve.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains - 7mm 2-Leg Chain-10mm 2-Leg Chain Slings – 13mm Bucket Chain -10mm Tamper Chain – Fall Arrest Block – Safety Harness – Lanyard – Mini Digger Sling – Mini Digger 2-Leg Chain Sling-Web Sling – 8mm 2-Leg Chain Sling

Identification mark of the equipment. 10mm Lashing Chains CR-01, CR-02, CR-03, CR-04, CR-05.– 7mm 2-Leg Chain SP1026 – 10 mm 2-Leg Chain 1085-1086-1087-13mm Bucket Chain 2454-10mm Tamper Chains TO3 – TO4 – Fall Arrest Block 18078458-Safety Harness 23034794-Lanyard 23034568.Web Sling. 8mm 2-Leg Chain Sling Mini Digger 180977.

Shared Trailer Chains. 10mm 1-Leg Chain Slings. SP 1126 – SP 1127 – SP 1128 – SP 1129.

Date of last thorough examination. Not Known.

No. of report issued on that date. Not Known.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn. 7mm 2-Leg Chain 2.12t – 13mm Bucket Chain 5.3 – 10mm 2-Leg Chain Slings 3.15t - Tamper Chains 63 Kn – Fall Arrest Block 140kg- Safety Harness – Lanyard 140kg – Mini Digger 8mm 2-Leg Chain Sling 2.8t-Web Sling 3t. Shared Trailer Chains 3.15t.

Details of any defects found (if any state). None.


Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 12-JUNE-2024, that the above particulars are correct.

Date for completion of next thorough examination. 12-DECEMBER2-2024.

Signature of Competent Person. 

Date. 12-JUNE-2024.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.