REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant owner.) Philip She	ovlin Plant H	lire LTD				
Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU						
Address at which the						
examination was made. As above						
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydraulic Excavator LIEBHERR See load Chart			Distinguishing Number K130283 Year of Manufacture. N/K Fleet No Giga L-0283			
Nature of Examination . 9(1)	9(2)	9(3)(a)(i)	9(3)	(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test. None						
Observations and conditions of ropes, chain:	s, attachment	s etc.				
Description		Condition			WLL	Pass Y/N
Auxiliary Lifting Point	•	Good			7500KGS	YES
RCI (for Test Load Results see SP-LAFT 01	1)	Good			N/A	YES
DIPPER PIN		Good			10000Kgs	YES
Quick Hitch		Good			10500Kgs	YES
None State description of the defect and any repair within a specified time. None.	r or renewal o	or alterations required	d to reme	dy the defe	ect either immedi	ately or
Other defects and remedies						
None						
Date of last thorough examination.						N/K
Latest date by which the next thorough examination must be carried out.						16.06.25
Date of thorough examination.						17.06.24
I certify that the above equipment was thoro to defects noted on this report, which are or Name and Address of Competent Person I Signature Qualifications. Fitter	could become	e a danger to persons	, the equ ss Compl	ipment is s	afe to operate.	
Name and Address of person authenticating	report if diffe	erent from above				
Signature			Date	17.06.24		
Date of report 17.06.24						

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01