REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

						. –	,	
Employer (and or plant of	owner.) Philip Sh	ovlin Plant I	Hire L7	TD				
Address. The Brook B Bennett Stre West Gorton Manchester								
Address at which the			· · · · · · · · · · · · · · · · · · ·					
examination was made.	As above							
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydraulic Excavator. TEREX See load Chart					Distinguishing Number. 180S301288 Year of Manufacture. N/K Fleet No 2228			
Nature of Examination.	9(1)	9(2)		9(3)(a)(i)	9(3)(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test.	None							
Observations and conditi	ons of ropes, chains	s, attachmen	ts etc.					
Description	Description		Condition			WLL		Pass Y/N
Auxiliary Lifting Point			Good			12000kgs		YES
RCI (for Test Load Results see SP-LAFT 01))	Good			N/A		YES
Quich Hitch 369961			Good			Lift Eye 10500kg		YES
Dipper Lift Point			Good			10000kg		YES
State description of the dwithin a specified time.	None efect and any repair None.	or renewal	or alte	rations required	to remo	edy the defe	ct either immedi	ately or
Other defects and remedi	es							
	None							
Date of last thorough examination.							29.09.23	
Latest date by which the next thorough examination must				rried out.				15.09.25
Date of thorough examination. 16.09.24								16.09.24
I certify that the above ed to defects noted on this re Name and Address of Co Signature	port, which are or	ould becom	ie a dai	nger to persons,	the equ Comple	ipment is sa	fe to operate.	
Qualifications. Fitter					2410			
Name and Address of per	son authenticating i	report if diff	erent f	rom above				
Signature					Date	16.09.24		
Date of report. 16.09.24								

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01