



**SRH LIFTING ENGINEERING**  
SALES-REPAIR-LOLER INSPECTIONS

**LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT**

RECORD No. SRH/6973-1.

Name of Company. SHOVLIN PLANT HIRE LTD.

Description of equipment. 10mm 4-LEG CHAIN SLINGS c/w 13mm EYE HOOK.

Identification mark of the equipment. 19773B, 24344A, D15841B, D15841A, UK10, UK756, UK757, UK1195, UK1196, UK1022, UK2788, 86044, D7491, 20611/1, 19761, 20611/2, 19431, 20611/3, 19531, 19631, 24344A, 20661, 24344B, SRH35, SRH36, SRH37, SRH38, SRH55, SRH56, UK2789, D11869, 83080A, 83080B, 83080C, 83080D, 87267/1, 87267/2, 87267/3, 87267/4, 87267/5, 87267/6, 87267/7, 87267/8, 87267/9, 87267/10, 19731.504, 2669, 84194, SRH 3471, 161125, 161126, 161127, 161128.

Date of last thorough examination. 15-07-24.

No. of report issued on that date. SRH/6828-1.

The Working Load Limits and (where relevant) corresponding radi. 6.7 tonnes @ 0° – 45°

Details of any defects found (if any state). None.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

**Declaration.**

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 2/3-DECEMBER-2024, that the above particulars are correct.

Date for completion of next thorough examination. 2/3-JUNE-2025.

Signature of Competent Person. *E. Maly*

Date. 2/3-DECEMBER-2024.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.