## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU  Address at which the examination was made. As above  Description of lifting equipment. 360 Wheeled Hydraulic Excavator Makers Name. Terex SWL & Configuration. See load Chart  Nature of Examination . 9(1) 9(2) 9(3)(a)(i)  Particulars of any test. None  Observations and conditions of ropes, chains, attachments etc.  Description Condition Auxiliary Lifting Point Good	Ye	stinguishing Numear of Manufactureet No	aber 180S301286 re. N/K 2227 9(3)(a)(iv)
Description of lifting equipment. 360 Wheeled Hydraulic Excavator Makers Name. Terex SWL & Configuration. See load Chart  Nature of Examination . 9(1) 9(2) 9(3)(a)(i)  Particulars of any test. None  Observations and conditions of ropes, chains, attachments etc.  Description Condition Auxiliary Lifting Point Good	9(3)(a)(ii)	ear of Manufactureet No	re. N/K 2227
Makers Name.  SWL & Configuration.  Nature of Examination .  9(1)  9(2)  9(3)(a)(i)  Particulars of any test.  None  Observations and conditions of ropes, chains, attachments etc.  Description  Auxiliary Lifting Point  Condition  Good	9(3)(a)(ii)	ear of Manufactureet No	re. N/K 2227
Particulars of any test. None  Observations and conditions of ropes, chains, attachments etc.  Description  Auxiliary Lifting Point  O(3)(3)(1)  O(3)(4)(1)  O(3)(4)(1)	F	9(3)(a)(iii)	9(3)(a)(iv)
Observations and conditions of ropes, chains, attachments etc.  Description Condition  Auxiliary Lifting Point Good			
Description Condition Auxiliary Lifting Point Good	MANAGANA		
Auxiliary Lifting Point Good			
		WLL	Pass Y/N
		10000kgs	YES
RCI (for Test Load Results see SP-LAFT 01) Good	·	N/A	YES
Puick Hitch S/N 281236 Good		5000Kgs	YES
State description of the defect and any repair or renewal or alterations required to within a specified time.  None.  Other defects and remedies	remedy the def	ect either immedi	ately or
None			
Date of last thorough examination.			16.04.24
Latest date by which the next thorough examination must be carried out.			08.04.26
Date of thorough examination.			09.04.25
I certify that the above equipment was thoroughly examined (unless otherwise state of defects noted on this report, which are of could become a danger to persons, the Name and Address of Competent Person Damian Schofield. Brook Business of Signature	ne equipment is s	safe to operate.	
Qualifications. Fitter			
Name and Address of person authenticating report if different from above			
Signature	Date 09.04.25		
Date of report 09.04.25			

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref:	SP LOLER 01