## REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employe	r (and or plant o	wner.) Philip Sho	vlin Plant H	lire L7	ΓD				
Address.	The Brook B Bennett Stree West Gorton Manchester								
	at which the								
examinat	ion was made.	As above							
Description of lifting equipment.  Makers Name.  SWL & Configuration.  360 Wheeled Hydra LIEBHERR See load Chart					ulic Excavator			stinguishing Num ar of Manufactur eet No	
Nature of	f Examination .	9(1)	9(2)		9(3)(a)(i)	9(3)(	(a)(ii) X	9(3)(a)(iii)	9(3)(a)(iv)
Particula	rs of any test.	None		•					
01				ta ata					
******		ions of ropes, chains	s, attachmen					Liti	Th MAI
Descripti				Condition				WLL 7500KGS	Pass Y/N
	y Lifting Point			Good				/500KGS N/A	YES YES
-		ilts see SP-LAFT 01	)	Good				10000Kgs	YES
DIPPER			*	Good Good				10500Kgs	YES
Geth Qu	ick Hitch			000	ou			105001423	1120
within a	specified time.	defect and any repai	r or renewal	or alto	erations required	i to reme	dy the def	ect either immed	iately or
Other de	fects and remed	ies							
		None							
Date of	last thorough ex	amination.							20.03.24
Latest date by which the next thorough examination mus					carried out.				11.03.26
Date of	thorough examin	nation.							12.03.25
to defect Name ar Signatur	ts noted on this and Address of C	report, which are or ompetent Person: D	could becon	ne a d	anger to persons	s, the equ	ipment is:	safe to operate. t Street, West Go	
Qualific									
Name at	nd Address of pe	erson authenticating	report if dif	fferent	from above				
Signatu	re					Date	12.03.25		
Date of	report 12.03.25								
terror.									

Issue No:	1
Issue Date:	Sept 2012
No of Pages:	Page 1 of 1
Document Ref	SPLOLER 01