REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant owner.) Philip Shovlin Plant Hire LTD

Address.

The Brook Business Complex

Bennett Street West Gorton

Manchester M12 5AU

Address at which the

examination was made. As above

Description of lifting equipment.

360 Wheeled Hydraulic Excavator

Distinguishing Number 180S301308 Year of Manufacture.

TEREX

Fleet No

N/K 2292

SWL & Configuration.

Makers Name.

See load Chart

Nature of Examination.

9(1)

9(2)

9(3)(a)(i)

9(3)(a)(ii) X

9(3)(a)(iii)

9(3)(a)(iv)

Particulars of any test.

None

Observations and conditions of ropes, chains, attachments etc.

Description	.L. Pass Y/N	Condition	WLL	Pass Y/N
Auxiliary Lifting Point	100kgs YES	Good	10000kgs	YES
RCI (for Test Load Results see SI	P-LAFT 01) YES	Good	N/A	YES
Quick Hitch S/N 200015 Geth	00Kgs YES	Good	5000Kgs	YES

Identification of any part found to have a defect which is or could become a danger to persons.

State description of the defect and any repair or renewal or alterations required to remedy the defect either immediately or within a specified time.

None.

Other defects and remedies

None

ate of last thorough examination.

26.05.24

Latest date by which the next thorough examination must be carried out.

21.05.26

Date of thorough examination.

22.05.25

I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Name and Address of Competent Person. Danian Schofield. Brook Business Complex, Bennett Street, West Gorton, Manchester.

Signature

Date 22.05.25

Qualifications. Fitter

Name and Address of person authenticating report if different from above

Signature

Date 22.05.25

Date of report 22.05.25

Issue No:	1	
Issue Date:	Sept 2012	
No of Pages:	Page 1 of 1	
Document Ref:	SP LOLER 01	