RRV 12 MONTHLY INSPECTION FORM

Examine / Check / Test each item listed below (use machine specific service manual & maintenance plan for information regarding inspection procedures and criteria). Indicate in the appropriate space below as each item has been performed. If the item is not found acceptable, describe each discrepancy in the comment space on the rear. Take immediate action to correct all discrepancies or remove machine from service.

Confirm Maintenance Plan Used

Giga SPMM 0007 Iss 2	Case SPMM 0001 Iss 4 / 5	924 AJH 146 Shovlin Iss3	Valtra RMQ60080V01 lss 2
Giga ZM50005083 Iss 2	Case SPMM 0001 Iss 6 / 7	924 HMM0015 Iss E	
	TD12 SPMM0005 lss 3 / 4	Evo MEWP SPMM 011 Iss2	

Cur	rent Hours 7 12 74	Plant Number	9015	
5)23)10	<u> </u>	Militario e del Associa del Trasco del III	9275	
Mad	thine Make & Type Gio men P	Serial Number	PB9275	
Item	Inspection / Check Detail		Result X - ✓ -	N/A
	All pre start checks	8 kg 158 (0) (82 g) (1) (0) (0) (0)		
2	Grease and lubricate as per maintenance plan			V
	All fluid levels correct, hydraulic, batteries, brake etc. Check			1
	Hydraulic cylinders, pivot pins, pivot points and hoses - Exar	mine		1
	Steering locks - Check			J
100 1 01	Trailer park brake pressure - Check/record pressure			AVCI
7	Service brake filter element - Renew			NUA
_	Brake system general - Check			<u> </u>
	Service brake - Test (3 dynamic tests or pull tests or torque	hub test)		V
	Service brake pressure - Check/record pressure			NG
	Rail wheel brake system - Examine			V,
	Parking brake - Test	enns# 1996	100 A	/
	Wheel nuts - Check			1/_
***************************************	Rail wheels - Check / Examine Complete SP WIRS 01			V V
***************************************	Rail wheels back to back - Check measurements (1358 - 13	363)		1/
	Rail wheel bearings - Check (spin / lift test)	DAVISTO CARROLA VARIA O CONTRACTO DE LA CONTRACTO	The state of the s	↓ ✓
	Rail wheel bearings - Examine if fault found during spin / lift	test		V
	Traction hubs - Check			NIA
	Road wheels and tyres - Examine			V
	Tyres to rail wheel interface-Examine	944124cm-000000000000000000000000000000000000	mich lackward in de le Amerika i pro vazonica na ze a mich con i populati	
	Rail bogie / axle pivots and trunnion - Examine			ν,
	Rail bogies / axles - Examine			V/
	Rail axle interlocks - Test (adjust if required)			Į į
***************************************	Dozer front bogie / trolley - Check			410
_	Dozer front bogie / trolley brake pads - Check			NIA
	Dozer front bogie / trolley brake - Check			-NG
	Emergency recovery system operation - Test			l V
	Operation of all lights - Check / Examine			<u> </u>
		and KCI Sounder les	t Results Sheet SP-HT 01	<i>.</i>
	Glass and wipers - Check	0008995 NEWALLORF (1935) WYSONYMATHA ERFORT (1		NW
	Safety labels - Check	-		₩-
	Recovery tow bar and hitches condition and security - Check			V .
	Underframe and super structure - components and welds - C	∠neck		1 ./
	Slew locks - Check		NET (COMPANY)	, Al A
	Rated capacity indicator - Test and complete data download		ar i loini and attach)	1011
	Visibility of paintwork and overall appearance, including yello	w panels - Check		V
	Trailer brake away siren - Test			1 1/
	Electrical components / connections / wiring - Check	g (ugunug) eggalen eer legt 100 (640).		V (20 V/20 10)
	Ballast weight - Check Farth band cables - Test and Examine using Registance Ob	mmotor 637474		11/
	Earth bond cables - Test and Examine using Resistance Oh	illineter 022424		<u> </u>
	Check valves - Check		ander generalisteren et er er er en en en er er	<i> </i>
42	Fire extinguisher - Examine		***************************************	∨

tem	Inspection /	Check Detail	Result X - ✓ -	N/A			
43	OLER cert / lifting accessories and safety devices - Check						
14	Auxiliary lifting point/s (if fitted) and decals - Examine						
15							
46	Machine cab file - Check						
	Tracks / running gear - Check			V			
	ALO device / Duel height limiter - Test and Examine						
49 Rail head scrapers - Examine							
-	Overload sounders - Check Complete Horn and RCI Sounder Test Results Sheet SP-HT 01						
_	Camera system - Check		Sept.	NIP			
	Basket and harness points - Examine			NIA			
	Torque hub brake adaptors - Examine			NIA			
04	Air Brake Pressure Check - Record Press	sure le test readings for Service Brake (SB) an					
th	rnatively, if conducting on track testing, of ne previous test then investigate / retest. I ck conditions can affect recording but mus	f any recordings are in the fail section inv	estigate and then retest.	Adverse			
Т	8			+++			
	FAIL			+++			
ומי	6		 	+++			
9			 	+++			
Meters	4 Speed Not Sufficient			\top			
=1	Minimum test speed PASS						
	must be over 6 KPH			$\perp \perp \perp$			
	0 1 2 3 4 5	6 7 8 9 10 11 12	13 14 15 16	17			
2	O 1 2 3 4 5 RIL BRAKE PULL TEST F			1			
		- 032 KSF					
CAI	LIBRATED TOOLS USED	1	Date	9			
САІ Гур	LIBRATED TOOLS USED e	Serial Number	Date	526			
yp	LIBRATED TOOLS USED e CLEA MCTO2	Serial Number 622424	Date 28	526			
yp	E MCTOR TORANE WRENCH	Serial Number	Date 28				
yp	LIBRATED TOOLS USED e CLEA MCTO2	Serial Number 622424 XK 18847	Date 28	526 .7.25			
ур	EARTH BOND TEST RESULTS	Serial Number 622424 XK 18847 55-7312 MACHINE IN CO	Date 28 25 24 24 DD OP(XX)	·526 ·7·25 ·11·25			
ур	EBRATED TOOLS USED E CELA MCTOR COROCH RAIL WHOM CAUNCE mments / Additional Work - Checks	Serial Number 622424 XK 18847 557312	Date 28 25 24 24 DD OP(XX)	·526 ·7·25 ·11·25			
yp yp Cor	EARTH BOND TEST RESULTS	Serial Number 622424 XK 18847 557312 MACHINE IN COR BRAVES TESTED F	Date 28 25 24 24 DD OP(XX)	·526 ·7·25 ·11·25			
Cor	EARTH BOND TEST RESULTS	Serial Number 622424 XK 18847 557312 MACHINE IN COR BRAVES TESTED F	Date 28 25 24 24 DD OP(XX)	·526 ·7·25 ·11·25			
yp yp Cor	EARTH BOND TEST RESULTS ipper End to Right Rail O.0213m \(\O \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \	Serial Number 622424 XK 18847 557312 MACHINE IN OZA BRAKES TESTED F	Date 28 25 24 25 24 25 26 27 28 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	526 17.25 11.25			
CAI Typ	EARTH BOND TEST RESULTS ipper End to Right Rail O.0213m \(\O \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \	Serial Number 622424 XK 18847 557312 MACHINE IN COR BRAVES TESTED F	Date 28 25 24 25 24 25 26 27 28 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	526 17.25 11.25			
Cor Di	EARTH BOND TEST RESULTS ipper End to Right Rail O.0213m \(\O \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \o \cdot \o \	Serial Number 622424 XK 18847 557312 MACHINE IN OZA BRAKES TESTED F	Date 28 25 24 25 24 25 26 27 28 28 29 20 20 20 20 20 20 20 20 20 20 20 20 20	526 17.25 11.25			