



# SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

## LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/7345-22.

Volvo Crane Wagon PN71 GYV- Steve.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains - 7mm 2-Leg Chain-10mm 2-Leg Chain Slings - 13mm Bucket Chain -10mm Tamper Chain - Fall Arrest Block - Safety Harness - Lanyard - Mini Digger Sling - Mini Digger 2-Leg Chain Sling-Web Sling - 8mm 2-Leg Chain Sling

Identification mark of the equipment. 10mm Lashing Chains CR-01, CR-02, CR-03, CR-04, CR-05.- 7mm 2-Leg Chain SP1026 - 10 mm 2-Leg Chain 1085-1086-1087-13mm Bucket Chain 2454-10mm Tamper Chains TO3 - TO4 - Fall Arrest Block 18078458-Safety Harness 23034794-Lanyard 23034568.Web Sling. 8mm 2-Leg Chain Sling Mini Digger 180977.

\*Shared Trailer Chains. 10mm 1-Leg Chain Slings. SP 1126 - SP 1127 - SP 1128 - SP 1129\*.

Date of last thorough examination. 17-MAY-2025.

No. of report issued on that date. SRH/7168-2.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn. 7mm 2-Leg Chain 2.12t - 13mm Bucket Chain 5.3 - 10mm 2-Leg Chain Slings 3.15t - Tamper Chains 63 Kn - Fall Arrest Block 140kg- Safety Harness - Lanyard 140kg - Mini Digger 8mm 2-Leg Chain Sling 2.8t-Web Sling 3t. Shared Trailer Chains 3.15t.

Details of any defects found (if any state). None.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

### Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 07-NOVEMBER-2025, that the above particulars are correct.

Date for completion of next thorough examination. 07-MAY-2026.

Signature of Competent Person. 

Date. 07-NOVEMBER-2025.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.



# SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

## LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/7345-21.

Scania Crane Wagon P1 SHV.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains - 10mm 2-Leg Chains - 10mm - 10mm Bucket Chain -

Identification mark of the equipment. 10mm Lashing Chains 0026I-0026J-0026G-0026E-2965 – 10mm Bucket Chain SRH/61- 10mm 2-Leg Chain Slings SRH/0050 – 0723 – 0724.

\*Shared Trailer Chains 10mm 1-Leg Chain Slings. SP1126 – SP 1127 – SP 1128 – SP1129\*.

Date of last thorough examination. 17-MAY-2025.

No. of report issued on that date. SRH/7168-3.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn.

10mm 2-Leg Chain Sling 3.15t

10mm Bucket Chain 3.15t.

Details of any defects found (if any state). None.

10mm 1-Leg Chain Slings. 3.15t.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

### Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 07-NOVEMBER-2025, that the above particulars are correct.

Date for completion of next thorough examination. 07-MAY-2026.

Signature of Competent Person. 

Date. 07-NOVEMBER-2025.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.