Record No DS 2467

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT Lifting Operations and lifting equipment regulation 1998 (Regulations 9)

Employer (and or plant owner.) Philip Sho	vlin Plant I	lire L'	ΓD				
Address. The Brook Business Complex Bennett Street West Gorton Manchester M12 5AU							
Address at which the examination was made. As above							
Description of lifting equipment. Makers Name. SWL & Configuration. 360 Wheeled Hydraulic Excavator. LIEBHERR See load Chart				Distinguishing Number K132511 Year of Manufacture. N/K Fleet No Giga L - 2511			
Nature of Examination . 9(1)	9(2)	ļ	9(3)(a)(i)	9(3)((a)(ii)	9(3)(a)(iii)	9(3)(a)(iv)
Particulars of any test. None							
Observations and conditions of ropes, chains,	, attachmen	ts etc.					
Description	Pass V/h	Con	dition		3	WLL	Pass Y/N
Auxiliary Lifting Point	YES	Goo				7500KGS	YES
RCI (for Test Load Results see SP-LAFT 01)		Goo				N/A	YES
DIPPER PIN	YES	Goo					
Geth Quick Hitch S/N 1158194	1770	Goo				10000Kgs 10500kgs	YES YES
within a specified time. None. Other defects and remedies							
None				5			
Date of last thorough examination.							12.11.24
Latest date by which the next thorough examination must be carried out.							06.11.26
Date of thorough examination.		1175					07.11.25
I certify that the above equipment was thorout to defects noted on this report, which are or consumer and Address of Competent Person. Dan Signature Qualifications. Fitter	ould becom	e a da	nger to persons	s, the equip s Complex	ment is s	afe to operate.	
Name and Address of person authenticating re	eport if diff	erent f	rom above				
gnature				Date 07.11.25			
Date of report 07.11.25							
			21.1				
			1		Issue No:		1
					Issue Dat		Sept 2012
					No of Pa		Page 1 of 1
					Documer	ii Kei:	SP LOLER 01