



SRH LIFTING ENGINEERING
SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/7508-17.

Scania Crane Wagon P1 SHV.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains -10mm 2-Leg Chains-10mm -10mm Bucket Chain-

Identification mark of the equipment. 10mm Lashing Chains 0026I-0026J-0026G-0026E-2965 – 10mm Bucket Chain SRH/61- 10mm 2-Leg Chain Slings SRH/0050 – 0723 – 0724.

Shared Trailer Chains 10mm 1-Leg Chain Slings. SP1126 – SP 1127 – SP 1128 – SP1129.

Date of last thorough examination. 07-NOVEMBER-2025.

No. of report issued on that date. SRH/7345-21.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn.
10mm 2-Leg Chain Sling 3.15t
10mm Bucket Chain 3.15t.

Details of any defects found (if any state). None. 10mm 1-Leg Chain Slings. 3.15t.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 24-APRIL-2026, that the above particulars are correct.

Date for completion of next thorough examination. 24-OCTOBER -2026.

Signature of Competent Person. *E Maly*

Date. 24-APRIL-2026.

Name and address of competent person and his employer, if appropriate (block letters).

E. Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.

+



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/7508-18.

Volvo Crane Wagon PO68 WBK.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains -8mm 2-Leg Chain- 7mm 2-Leg Chain- 3t Web Sling – Bucket Chain – 10mm 2-Leg Chain Slings -10mm Tamper Chain – Fall Arrest Block – Safety Harness – Lanyard.

Identification mark of the equipment. 10mm Lashing Chains SRH/0037-SRH/0038-2967-2968-2966-0026F 2966F – 8mm 2-Leg Chain 160320 – 7mm 2-Leg Chain SP1016 – 10mm 2-Leg Chain Slings PO70 – PO68 SRH/0035-10mm Bucket Chain SRH/62-10mm Tamper Chains TO1 – TO2 – Fall Arrest Block 8676100 Safety Harness 23559295- Lanyard 23558409 – Mini Digger Web Sling AF3S 0918.

Shared Trailer Chains. 10mm 1-Leg Chain Sling – SP 1126 – SP 1127 – SP 1128 – SP 1129.

Date of last thorough examination. 07-NOVEMBER-2025.

No. of report issued on that date. SRH/7345-21.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn. 7mm 2-Leg Chain 2.12t – Bucket Chain 3.15t – 8mm 2-Leg Chain Sling 2.8t – 10mm 2-Leg Chain Slings 3.15t Tamper Chains 63 Kn – Fall Arrest Block 140kg- Safety Harness – Lanyard 140kg – Mini Digger Web Sling 3t Shared Trailer 10mm 1-Leg Chain Slings 3.15t.

Details of any defects found (if any state). None.

Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 24-APRIL-2026, that the above particulars are correct.

Date for completion of next thorough examination. 24-OCTOBER-2026.

Signature of Competent Person. 

Date. 24-APRIL-2026.

Name and address of competent person and his employer, if appropriate (block letters).

E. Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.



SRH LIFTING ENGINEERING

SALES-REPAIR-LOLER INSPECTIONS

LOLER 1998. REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT & PLANT

RECORD No. SRH/7508-19.

Volvo Crane Wagon PN71 GYV- Steve.

Name of Company. Shovlin Plant Hire Ltd. Brook Business Complex, Bennett St, West Gorton, Manchester.

Description of equipment. 10mm Lashing Chains - 7mm 2-Leg Chain-10mm 2-Leg Chain Slings – 13mm Bucket Chain -10mm Tamper Chain – Fall Arrest Block – Safety Harness – Lanyard – Mini Digger Sling – Mini Digger 2-Leg Chain Sling-Web Sling – 8mm 2-Leg Chain Sling

Identification mark of the equipment. 10mm Lashing Chains CR-01, CR-02, CR-03, CR-04, CR-05.– 7mm 2-Leg Chain SP1026 – 10 mm 2-Leg Chain 1085-1086-1087-13mm Bucket Chain 2454-10mm Tamper Chains TO3 – TO4 – Fall Arrest Block 18078458-Safety Harness 23034794-Lanyard 23034568. Web Sling. 8mm 2-Leg Chain Sling Mini Digger 180977.

Shared Trailer Chains. 10mm 1-Leg Chain Slings. SP 1126 – SP 1127 – SP 1128 – SP 1129.

Date of last thorough examination. 07-NOVEMBER-2025.

No. of report issued on that date. SRH/7345-22.

The Working Load Limits and (where relevant) corresponding radi. 10mm Lashing Chains 63 Kn. 7mm 2-Leg Chain 2.12t – 13mm Bucket Chain 5.3 – 10mm 2-Leg Chain Slings 3.15t - Tamper Chains 63 Kn – Fall Arrest Block 140kg- Safety Harness – Lanyard 140kg – Mini Digger 8mm 2-Leg Chain Sling 2.8t-Web Sling 3t. Shared Trailer Chains 3.15t.

Details of any defects found (if any state). None.


Date by which the defects above should be rectified. N/A

Conditions if any which should be observed / other observations. None.

Declaration.

I hereby certify that thorough examination of the equipment described in this report was completed in accordance with LOLER 98 Regulations on, 24-APRIL-2026, that the above particulars are correct.

Date for completion of next thorough examination. 24-OCTOBER-2026.

Signature of Competent Person. 

Date. 24-APRIL-2026.

Name and address of competent person and his employer, if appropriate (block letters).

E.Maly. SRH Lifting Equipment. Brook Business Complex, Bennett St; West Gorton, Manchester. M12 5AU.